Notice

Model:



Effective from : Chassis No. P32649-06

Category: COLOR	TELEVISION	Date: _	OCTOBER / 12 / 2009	
Please add this noti	ce to the Service Manual listed belov	٧.	REVISION 0	_
CORRECTION SERVICE FLASH	● PRODUCTION CHANGE■ ADD INFORMATION		FILE NO.	_ _
	E PROPLICTION CHANGE		IIII	

Destination: U.S.A. / CANADA REF : No. SM780159-06

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P32649. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P32649-00 used in Model DP32649 (SM780159).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

DP32649

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be changed from 10h to 15h in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

Page &

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 18, Chassis Electrical Parts List	▲ EL901	Old	1AV4T40C05000	LCD(T315XW02 VS)	1	NO	D
		New	1AV4T40C15000	LCD(AX080B058G)	1	NO	
Page 14, Chassis Electrical Parts List	R888	Old	RGFR000ZTCANL	MT-GLAZE 0 ZA	1	NO	D
		New	N/A	NOT USED	0	NO	
	R890	Old	RGFR000ZTCANL	MT-GLAZE 0 ZA	1	NO	D
		New	N/A	NOT USED	0	NO	
	R891	Old	N/A	NOT USED	0	NO	D
		New	RGF4702JTCANL	MT-GLAZE 47K JA	1	NO	

© Sanyo Manufacturing Corporation 2009

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 14, Chassis Electrical Parts List	R893	Old	N/A	NOT USED	0	NO	D
		New	RGF4702JTCANL	MT-GLAZE 47K JA	1	NO	
Page 18, Chassis Electrical Parts List	▲ WK5LV −PN	Old	1LB4W30B16500	CORD, 30P-30P(LVDS)	1	NO	D
		New	1LB4W30B19900	CORD, 30P-30P(LVDS)	1	NO	

© Sanyo Manufacturing Corporation 2009

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

September 2009 SMC